

Rent Reveal Report

Address: ***** STREET

311 Service Requests (148)

Finding 1

Problem Descriptor: CEILING

Problem Type: PAINT/PLASTER

Status: Open

Created Date: 2025-04-11T12:24:49.000

Resolution Description: The Department of Housing Preservation and Development conducted an inspection for the following conditions and identified potential lead-based paint conditions. HPD will attempt to contact you to schedule a follow-up inspection to test the paint for lead.

Resolution Action Updated Date: 2025-04-11T00:00:00.000

Finding 2

Problem Descriptor: ENTIRE BUILDING

Problem Type: HEAT/HOT WATER

Status: Open

Created Date: 2025-04-11T12:24:49.000

Resolution Description: The following complaint conditions are still open. HPD has attempted to notify the tenant. The original complaint is still open, and HPD may only need to confirm that the condition exists by inspecting one apartment. If we cannot contact the tenant from the original complaint or get access to that apartment, HPD may attempt to contact the person who filed this complaint to verify the correction of the condition or may conduct an inspection of your unit. You can check HPDONLINE.

Resolution Action Updated Date: 2025-04-11T00:00:00.000